



1016 Windward Ridge Parkway
Alpharetta GA 30005

Office: 770-643-8501
Fax: 770-643-8820
www.crystaltek.us.com

How To Use Adhesive-Off

ADHESIVE-OFF is a safe ready to use product designed to quickly remove adhesive, grease, asphalt, tar, paint overspray, printing inks, and gum from multiple substrates: metal, glass, canvas, FRP, gel coat, fiberglass, etc. Adhesive-Off is a commercial grade product with over 90% active ingredients. Its new VANILLA SMASH scent is widely preferred over the strong citrus odor of competing products, especially for indoor use. Contains no caustics, acids, or known carcinogens. Not recommended for use on fabrics. Do not soak carpet because it may affect the adhesive backing!

Step by Step

1. Thoroughly drench dry adhesive:
 - *Spraying preferred, but a product soaked cloth works fine.*
2. Allow about 1 minute dwell time. You should see the adhesive swell visibly.
 - *Works best over 50 degrees F.*
 - *Product may dry off quickly if used in hot-dry weather. Re-soak as needed.*
3. Pressure wash, scrape, or wipe off.
 - *Depending on the size of the job, different removal methods can be used. For BIG jobs, a pressure washer or power hose works well. For medium jobs, scrape from bottom to top. For small jobs, wipe off with a paper towel or other clean cloth. A scrub brush works great around rivets, etc.*
4. Re-apply as needed.
 - *Thick layers of adhesive may require multiple applications for full removal.*
5. Prepare surface in traditional manner for new application
 - **Ghost-Off is great if the surface is oxidized**
 - **½ rubbing alcohol, ½ water works well for prepping a regular surface.**

